



No.TQC/HYD/Pur/Wooden Crates/AP/2018-19

Dt.04-09-2018

CORRIGENDUM

The following diagram has been depicted at page No.43 of tender bearing No. TQC/HYD/Pur/Wooden Crates/AP/2018-19, dt.28-08-2018:

•		•		•		•
•		•		•		•
•		•		•		•

In supersession of the above diagram, the revised diagram shall be as under:

••		••		••		••
••		•		•		••
••		•		•		••
••		••		••		••

Note: There is no change in the specifications. Nails shall be 28 Nos. in all, as prescribed at point No.7, page 42 of tender document.

REGIONAL MANAGER